For questions or assistance, please contact Dave Tinkle:
davetinkle@brundagebone.com | (602) 558-2412

For questions or assistance, please contact Dave Tinkle:
davetinkle@brundagebone.com | (602) 558-2412

For questions or assistance, please contact Dave Tinkle:
davetinkle@brundagebone.com | (602) 558-2412

Pump Evaluation

Date: 09/23/2026 Unit: 3758 Location: Loxley Al.

Pump Make: SANY Size: 66M Pump Kit: Boom: SY66 6-Sec

Pump Model: Pump SN: BC56OOCA1632 Pump Year: 20

Truck Make: MACK Truck Model: TE64 Truck Year: 21

Truck VIN: IM2TE4GC3MMOO5807

Engine Make: MACK Engine Model: MP8

Trans Model: MAXITORQUE Trans Make: MACK

Truck Hours: 4833 Truck Miles: 42,003 Pump Hours: 1940

Percentage and/or Explanation

Truck Condition: GOOD

Tires: Front 75% REAR 80% Suspension: GOOD

Brakes: 75% Exhaust: GOOD

Engine: RUNS AS IT SHOULD Transmission: GOOD

Transfer Case: Works as it should Valve Adj:

DOT: 04/2026 Leaks: NONE 100%

Paint: GOOD 85% Cleanliness: CLEAN 85%

Percentage and/or Explanation

Pump Condition: GOOD

Wear Parts: GOOD 80%

Barrels: GOOD 80%

Diff Cyls: GOOD

Pump Pressure: 350 bar

Pipe: GOOD 90%

Hyd. Cyls: GOOD

Hand-Valves: GOOD

Hyd. Oil: CLEAR

Agitator: GOOD 70%

Hopper: GOOD

Accumulator: good

Boom Inspection: 05/23/2026

Remote Boxes: GOOD (2)

Auto Greasers: GOOD

Overall Operation:

RUNS AND OPERATES AS IT SHOULD

Recent Major Repairs:

Truck: NONE NEEDED

Pump: boom replaced 2025

Photos needed from all four corners showing:

1)Complete truck in photo 2) Photo showing inside hopper 3) Photo showing both remotes and reel

HOURS AND MILES MAY NOT BE ACCURATE DUE TO MAINTANCE REPLACEMENT.